



Motorized Pulley 138E, Ø 5.45 in. (138 mm)

Motorized Pulley 138E, with machined helical gearbox, performs with a gearbox efficiency of 95% of nominal power, in a compact diameter of 5.45 inches. With a minimum roller length (RL) of 11.81" and powers ranging from 0.13 to 1.0 HP, this Motorized Pulley is suitable for most small diameter applications. These include:

- Light agricultural conveyors
- Light C & D debris conveyors
- Mobile and portable conveyors

Motorized Pulley 138E features a standard enclosure class of IP66/67 and is also available in stainless steel for wash down applications.

STANDARD SPECIFICATION of Motorized Pulley

- Crowned mild steel 5.45" shell treated with anti-rust wax
- Die cast aluminum bearing housing
- Mild steel shaft treated with anti-rust wax
- Die cast lightweight aluminum gearbox housing
- Sealing system – degree of protection IP66/67 (EN60034-5.) See page 88.
- Compact die cast aluminum terminal box with WAGO connectors
- Voltage: All common voltages available. Please specify.
- Three phase induction motor
- One out of two oil plugs is fitted with a magnet to filter the oil.
- Motor winding insulation class F
- Dynamically balanced rotor
- Oil change recommended every 10,000 operational hours
- Maximum RL 70.87"
- Non standard RL lengths available
- Single phase is available in 0.33, 0.50, and 0.75 HP, supplied with a running capacitor
- To be used in the horizontal position only.

STAINLESS STEEL options

TS7N

- Stainless steel shell – AISI 304 range
- Stainless steel shafts – AISI 303 range
- Stainless steel covered aluminum bearing housings – AISI 304 range
- Stainless steel oil plugs with magnet – AISI 304 range
- Compact stainless steel terminal box – AISI 304 range
- Alternatively, straight stainless steel connector – AISI 303 range with power cord.
- Regreasable stainless steel seals – AISI 303 range
- Degree of protection IP66/67 (EN60034-5.) See page 88.
- FDA & USDA food grade grease
- Option: FDA & USDA food grade recognized oil.
- Special mounting brackets are available

Please note:

- **Noise-sensitive Areas:** High speed 2-pole motors can cause higher noise levels and are not recommended for noise-sensitive areas
- **Technical Precautions for Design, Installation, and Maintenance:** pages 76-86
- **Environmental Considerations:** page 72
- **Optional Extras:** pg 9 and back cover
- **Electrical Connection Diagrams:** pages 94-96.